
#### Goldsborough Creek

#### Dam Removal and Stream Restoration

**Mason County, Washington** 






- Project Sponsored by U.S. Army Corps of Engineers and Washington State Department of Fish and Wildlife
- Design prepared by Tetra Tech, Inc. ISG
- Presented by Krey H. Price, P.E.



#### **Project Location**








#### Project Background

**Dam History** 



- Dam Built in 1921
- Modified in 1932

- Abandoned in 1950's
- Stabilized in 1997







#### Project Background

**Existing Dam** 



- Upstream Siltation
  - No Storage

Downstream ErosionImpedes Fish Passage





#### Project Background

Feasibility Study



- Feasibility Report completed by U.S. Army Corps of Engineers in 1999
- Recommendation: Replacing existing dam with 33 sheet pile weirs in 7 groups spanning 2000 feet of channel





## Design Analysis Fisheries

- Existing fish ladder ineffective for most species
- Target species is Chum Salmon
- Maximum drop height 1 foot








# Design Analysis Hydraulics

- HEC-RAS Analysis
  - Model incorporated various alignments and weir configurations
- Local Analyses
  - Stream banks at weirs
  - Stream invert at weirs





## Design Analysis Sedimentation

#### Sampling:

- Sieve Analyses
- Pebble Counts






6" Grid Shown





### Design Analysis Sedimentation






### Design Analysis Geotechnical

Kitsap Formation

Wetlands






## Design Analysis Demolition

#### Material

- Timber (Dam and Fish Ladder)
- Sheet Pile
- Concrete
- Unknown Quantities










#### Stream Restoration

#### **General Plan**








### Stream Restoration General Profile

- 7 Weir Groups
- Cut and fill areas
- Existing S = 0.5%
- Design S = 2.5%








## Stream Restoration Weir Plan

- 20° Dogleg
- Width Varies








### Stream Restoration Weir Profile

- Preformed Scour Holes:
  - Subsurface riprap
  - Common fill
  - Stream cobble
- Compaction Zones






# Stream Restoration Weir Section (cut)

- Channel Invert Protection
- Common Fill

- Stream Cobble Layer
- Low-flow Notch








May 2000

# Stream Restoration Weir Section (fill)

- Channel Invert Protection
- Common Fill


- Stream Cobble Layer
- Low-flow Notch




### Stream Restoration Weir Details

#### Weir Cap

- Shape
- Material










### Stream Restoration Weir Details

H-Pile vs. Sheet Pile








#### Stream Restoration Bank Protection

- Type 1 Riprap 18" layer, D50 = 12"
- Type 2 Riprap -36" layer, D50 = 24"
- Type 3 Riprap -54" layer, D50 = 36"
- Fabric-Wrapped Reinforced Soil Lifts









May 2000

## Stream Restoration Habitat Features

- Large Woody Debris
- Boulders









### Stream Restoration Additional Considerations

- Temporary Diversion
- Railroad Trestle
- Downstream Utilities





### Construction Summer 2001

- Mobilization
- Stream Diversion / Fish Capture
- Clearing and Grubbing







#### Construction













## Construction Misc. Construction Photos

- Pile Driving
- Concrete Forms
- Habitat Features







## Construction Lessons Learned

- Check
- Recheck
- Check Again







# Construction Final Grading

- Rewatering
- Revegetation





## Stream Restoration Summary

- Project provides balance between fisheries needs and hydraulic requirements
- Current status: construction nearing completion
- Rewatering scheduled for September 21, 2001

#### Acknowledgements

- U.S. Army Corps of Engineers, Seattle District
- Washington State Department of Fish and Wildlife
- Previous Studies by Simpson Timber Company



